


Cable Length Measurement Method



Confidence. Engineered.


Male/Female
Connector



Male/Female
Connector

When measuring cable length with two connectors (male/female) at each end, the reference points for measurement will be the edge of one connector and the edge of the other.


Right Angle
Connector



Male/Female
Connector

When measuring cable length with a right-angle connector at one end, the center of the right-angle connector will be considered the reference point for measurement.


Male/Female
Connector



Edge of
PCBA

When measuring cable length with the cable assembled to an embedded antenna, the PCBA edge will be considered the reference point for measurement.

Male/Female
Connector



Edge of
Grommet

When measuring cable length with the cable assembled to an antenna or device, the edge of the grommet will be considered the reference point.